Ohio EPA - Daily Discharge Monitoring Report - Form 4500

SUBMISSION ID:

FACILITY:

LOCATION:

COUNTY:

DISTRICT:

142711

American Energy Corp - Century Mine

43521 Mayhugh Hill Rd Twp Hwy 88 Beallsville, OH 43716

SEDO

STATUS:

Original

PERMIT NUMBER:

STATION CODE: MONITORING PERIOD: REPORTING LAB: 0IL00091*GD 015 2010-11-01 To: 2010-11-30

TraDet

William Thompson ANALYST:

NO DISCHARGE INDICATOR:

PARAMETER	Manganese, Total					1	
PARAMETER CODE	(Mn) 01055	<u> </u>		<u> </u>	-}	}	
UNITS	ug/l	<u> </u>		\ <u></u>		<u> </u>	}
FREQUENCY	1/2 Weeks						
SAMPLING TYPE	Grab	ļ	[ļ		<u> </u>	
2010-11-01	<u> </u>	<u> </u>	<u> </u>	ļ	<u> </u>		
2010-11-02	469						
2010-11-03	ļ	ļ				1	
2010-11-04	<u> </u>	<u> </u>					
2010-11-05	<u> </u>						
2010-11-06							
2010-11-07							
2010-11-08							
2010-11-09							
2010-11-10						<u> </u>	
2010-11-11							
2010-11-12							
2010-11-13							
2010-11-14							
2010-11-15	300						
2010-11-16							
2010-11-17							
2010-11-18							
2010-11-19							
2010-11-20							
2010-11-21							
2010-11-22							
2010-11-23							
2010-11-24							
2010-11-25							
2010-11-26							
2010-11-27							
2010-11-28							
2010-11-29							
2010-11-30							
Minimum	300.0						(((((((((((((((((((
Maximum	469.0						
Average	384.5				1		
Count Name of Responsible Officia	2				Signature of Responsible	Official or Authorized	Submission
or Authorized Representative		nalty of law that I have po submitted herein and base	ersonally examined and ed on my inquiry of tho	am ramma	Represe	ntative	Date/Time
Cody Mozena	individuals immediately responsible for obtaining the information. I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment. Page 12						2010-12- 14 11:12